



Calibration of Verifone MX915/925

1. Power on device
2. Press the 1, 5, and 9 buttons on the keypad simultaneously for 2 seconds.
 - a. This step only needs to be performed if an application has been loaded to the device.
3. Once the device displays the login menu, press the red "X Cancel" button.



- a.
4. This will bring you to a menu where you are presented different options.
 5. Press option "2" for calibration option.
 6. DO NOT TOUCH SCREEN DURING CALIBRATION PROCESS.
 7. Once the calibration is done, press the green "O Enter" button to navigate back to the login menu.
 8. From here, you can either reboot the device, or login and perform other functions.